

**From:** [Garyg Miller](#)  
**To:** [Rita Engblom](#)  
**Subject:** Re: Gulfco Haz Mat Under Cap  
**Date:** 12/21/2010 03:29 PM

---

No; there was sludge left when the impoundments were closed in 1982 (the sludge was mixed w/ clay & "solidified"), but no samples were taken during the RI/FS to protect cap integrity; however, the shallow ground water contamination came from the former impoundments and will be the same chemicals as contained in the sludge.

Gary Miller, P.E.  
Remediation Project Manager  
EPA Region 6 - Superfund (6SF-RA)  
(214) 665-8318  
[miller.garyg@epa.gov](mailto:miller.garyg@epa.gov)

▼ [Rita Engblom---12/21/2010 03:22:39 PM---You don't have anything on contaminants within the impoundment? Rita Engblom](#)

**From:** Rita Engblom/R6/USEPA/US  
**To:** Garyg Miller/R6/USEPA/US@EPA  
**Date:** 12/21/2010 03:22 PM  
**Subject:** Re: Gulfco Haz Mat Under Cap

---

You don't have anything on contaminants within the impoundment?

---

Rita Engblom  
1445 Ross Avenue (6SF-PR)  
Dallas, TX 75202

214-665-8341 (work)  
214-789-2302 (cell)  
214-665-7447 (fax)

▼ [Gulfco Haz Mat Under Cap](#)

**Gulfco Haz Mat Under Cap**

**Garyg Miller** to: Rita Engblom

12/21/2010  
03:08 PM

---

Rita - see paragraph #19 in the draft AOC below .

Thanks,

Gary Miller, P.E.  
Remediation Project Manager  
EPA Region 6 - Superfund (6SF-RA)  
(214) 665-8318  
miller.garyg@epa.gov

[attachment "draft Gulfco Cap Repair Removal AOC-1 12-15-2010.docx" deleted by Rita Engblom/R6/USEPA/US]